



Assembly Line




Uppers with buttresses and toe caps applied, ready for lasting

Stock of stitched uppers ready for application of buttresses - toe caps

From the stitching department

See Lasting Line



Exit from the conveyor, ready for loading in finishing.